



Date 11/27/2019

Revision	Date

**THE GLENN**  
Orlando, Florida



**BUFFER CONCEPT**  
Rocking Horse Road

Sheet Number



EXISTING CONDITION



SWEET VIBURNUM HEDGE



PROPOSED TREATMENT



CONFEDERATE JASMINE BUFFER

**BUFFER A**

**EXISTING CONDITION:**

- THIS PORTION OF THE EXISTING BUFFER CONSISTS OF SEVERAL MATURE LIVE OAKS AND TURKEY OAKS AND MATURE SPALM PALMS AS THE CANOPY
- THE GROUND PLANE IS MOSTLY OPEN WITH SEVERAL JAVIERE SPALM PALMS WITH NO CLEAR TRUNK
- THE EXISTING TREES ARE IN GOOD CONDITION BUT THERE ARE LOTS OF VINES AND BROKEN BRANCHES AND DEAD WOOD.
- SOME INVASIVE WEED TREES ARE PRESENT
- THERE IS AN EXISTING 8 FT. TALL CHAIN LINK FENCE IN FAIR CONDITION WITH INVASIVE VINES COVERING PORTIONS OF IT

**PROPOSED TREATMENT:**

- REMOVE ANY DEAD OR DYING TREES AND PRUNE OUT DEAD WOOD AND CROSSING BRANCHES
- REMOVE ALL WEED TREES
- REMOVE ALL GROUND PLANE DEBRIS, LEAVING ONLY THE DESIRED TREES AND PALMS
- REMOVE ALL VINES FROM THE EXISTING TREES AND FENCE
- PRUNE PALMS TO REMOVE DEAD FRONDS
- REMOVE WEEDS AND PROVIDE A NEW LAYER OF MULCH TO SUPPRESS WEEDS IN THE FUTURE
- REPLACE CHAIN LINK FENCE WITH A NEW CHAIN LINK FENCE
- PLANT CONFEDERATE JASMINE ALONG THE FENCE (2 FT. APART) TO GROW TOGETHER AFTER ONE GROWING SEASON AND PROVIDE A CONTINUOUS SOLID SCREEN ALONG THE ENTIRE LENGTH OF THE BUFFER

**BUFFER B**

**EXISTING CONDITION:**

- THIS PORTION OF THE EXISTING BUFFER CONSISTS OF SEVERAL MATURE LIVE OAKS AND TURKEY OAKS AND MATURE SPALM PALMS AS THE CANOPY
- THE GROUND PLANE IS COMPLETELY COVERED BY PLANT MATERIAL AND SHRUBS AS A SOLID VISUAL BUFFER FOR THIS PORTION OF THE SITE
- THE GROUND PLANE MATERIAL CONSISTS OF TERNIS, PHLOEOCORCH, YOUNG PALMS AND YOUNG OAK TREES
- THERE IS AN EXISTING 8 FT. TALL CHAIN LINK FENCE IN FAIR CONDITION WITH INVASIVE VINES COVERING PORTIONS OF IT

**PROPOSED TREATMENT:**

- IT IS NOT RECOMMENDED TO DO MUCH WITH THIS PORTION OF THE BUFFER. IF IT ALREADY SERVES AS A SOLID VISUAL BUFFER, ANY FURTHER MAINTENANCE ACTIVITY WITHIN THE BUFFER WOULD COMPROMISE THE QUALITY OF THE EXISTING GROUND PLANE MATERIAL.
- REMOVE OBVIOUS DEBRIS SUCH AS FALLEN BRANCHES OR TRUNKS
- REPLACE CHAIN LINK FENCE WITH A NEW CHAIN LINK FENCE
- PLANT CONFEDERATE JASMINE ALONG THE FENCE (2 FT. APART) TO GROW TOGETHER AFTER ONE GROWING SEASON AND PROVIDE A CONTINUOUS SOLID SCREEN ALONG THE ENTIRE LENGTH OF THE BUFFER